



Gibraltar Maritime Administration

HM Government of Gibraltar

Watergate House
2/8 Casemates Square
Gibraltar

Tel (+350)200 46862 / 200 47771 /200 50424
Fax (+350) 200 47770
e-mail: maritime.survey@gibraltar.gov.gi
maritime.registry@gibraltar.gov.gi

Shipping Information Notice – 084

Code of Safe Working Practices for Merchant Seafarers: Amendment 2020

To: Ship owners, Operators, Managers, DPA's

This Shipping Information Notice provides information about the 2020 amendments to the U.K. Code of Safe Working Practices for Merchant Seafarers (“the Code”).

The Code provides best practice guidance for health and safety on board ship. It also gives guidance on safety management and identifies statutory duties underlying the advice and includes practical information for safe working on board.

Amendment 1 reflects editorial alterations only.

1. Introduction

- 1.1 An amendment to the U.K. Code of Safe Working Practices for Merchant Seafarers (“the Code”) was issued on 26th November 2020 after consultation with industry.
- 1.2 The Code is an authoritative best practice manual on health and safety on board ships. Gibraltar Maritime Administration endorses the code for health and safety on board ships, and gives practical information on safe working.
- 1.3 The Code is included within the publications carriage requirements of Shipping Guidance Notice – 042, as an alternative to the ILO Code of Practice for Accident Prevention.

2. Amendments

- 2.1 The following table summarises the changes that have occurred in the 2019 4th Edition of the Code, following public consultation and review by the COSWP Working Group, which consists of representatives of the shipping industry, seafarers and seafarers’ unions in collaboration with UK MCA policy leads.
 - 2.2 In addition, in various chapters references have been updated and typographical corrections made.
-

Chapter	Title / Paragraph Number (old reference if altered)	Reason for 2020 Amendment	2020 Amendment Title / Paragraph Number
Chapter 4 - Emergency Drills and Procedures	New section and Annex	To add current guidance on Damage Control Drills and clarification of drills per vessel class	4.13 Damage Control Drills - New section
			Annex 4.1 Table of Emergency Drills and their Frequency
Chapter 5 - Fire Precautions	5.3 Electrical and other fittings	Stakeholder engagement comment	5.3.5 Amended wording
Chapter 6 – Security On Board	6.1 Introduction	Reference review	6.1.1 MCA's Wellbeing at Sea: A guide for organisations, Chapter 3.3, and Wellbeing at Sea: A pocket guide for seafarers, Chapter 2.5.
Chapter 9 - Safety Signs and their Use	9.1 Introduction	Chapter reviewed to reflect requirements of IMO Resolution A.1116(30)	9.1 Referencing 9.1.1 Additional final sentence
Chapter 11 - Safe Movement Onboard Ship	11.5 Lighting	To reflect HSG38 – Lighting at Work and current guidance	11.5.2 Grammatical amendment
			11.5.3 Section reviewed
			Annex 11.2 Lux values and bullet points updated
Chapter 12 - Noise, Vibration and Other Physical Agents	12.1 General Advice	Chapter review in light of HSE Hand, Arm Vibration (HAV) Guidance 2019	12.1.1 Reference to MCA's Wellbeing at Sea: A guide for organisations, Chapter 3.7.
	12.2 Prevention or control of exposure to a physical agent		12.2.2 Bullet (1) 12.2.6 Amended wording
	12.12 Determining Vibration Levels		12.12.8 & 12.12.9 New sections relating to vibration exposure limit values (ELVs)
	12.14 Mitigation		12.14.7 Section reviewed.
	Annex 12.2 Daily Exposure to Different Sound Levels		Annex 12.2 Updated guidance to IMO Resolution MSC337(91) Code on Noise Levels onboard Ships
Chapter 15 - Entering Dangerous Spaces (Enclosed Spaces)	15.6 Testing the Atmosphere of the Space	Red Ensign Group Yacht meeting enquiry concerning SOLAS Chapter X1-1 – Portable Atmosphere Testers, as applicable to yachts.	15.6.5 Amended wording for guidance on monitoring equipment 15.6.6 New section reflecting guidance for smaller vessels.
	15.6.11 Testing for toxic gases	All sections reviewed to follow current guidance.	15.6.12 Testing for toxic gases; Amended wording and includes adjustment for testing for specific contaminants ' <i>such as benzene or hydrogen sulphide</i> ' 15.6.13 New summary section with table outlining the conditions to be tested as a minimum, following current limits within EH40 as of August 2020. https://www.hse.gov.uk/pubns/books/eh40.htm

15.14 Preparation for an Emergency	Customer enquiry into the use of Emergency Escape Breathing Equipment (EEBD) when carrying out a rescue. Sections reviewed to follow current guidance.	15.14.5 Amended wording to consider what rescue equipment is needed. 15.14.8 Amendment of section to clarify use of EEBD during a rescue. 15.14.9 New section; 'When entering a space to carry out a rescue, it is important to ensure that the area adjacent to the space of entry is free from any hazard and cordoned off accordingly'.
18.17 Portable power- operated tools and equipment	Stakeholder engagement comment	18.17.2 Amended section 18.17.3 Amended section 18.17.4 Amended section
20.2 General	To reflect current guidance and stakeholder engagement comments	20.2.4 Addition of 'prevented from' 20.2.8, 20.2.9 & 20.2.10 New sections to reflect requirements for the isolation of power sources
20.9 Refrigeration machinery and refrigerated compartments		20.9.1 Addition to sentence 'or having first completed a permit to work (PTW), as part of the risk assessment process.' 20.9.2 Addition to sentence 'and appropriate PPE should be worn when undertaking any task involving the handling of chemicals'.
20.10 Steering Gear	Section reviewed to reflect the requirements of planned maintenance of 'critical equipment'.	20.10 New title - Critical equipment.
		20.11 Steering Gear – section reviewed
20.11 Hydraulic and pneumatic equipment		20.12 Hydraulic and pneumatic equipment
20.12 Electrical Equipment 20.12.1	Lock Out Tag Out (LOTO) safety guidance	20.13 Electrical Equipment 20.13.1 Replaced word 'wetness' with 'moisture' Review of wording 'as low as 60V' to 'of 60V or lower' 20.13.3 New section - Lock out, tag out
20.12.3 20.12.4	Stakeholder engagement comment	20.13.7 Addition of wording 'the energy source should be isolated and any residual energy dissipated first'. Addition of reference to LOTO. 20.13.8 new heading 'Other Precautions' Additional wording to section.

20.12.6	Stakeholder engagement comment	20.13.10 Amendment to first bullet point 'electrically competent and trained in first aid'.
20.14.2 Definitions	Amended to include LOTO	20.15.2 Definitions Addition of new definition - LOTO: Lock out, Tag Out
20.14.12 Notices		20.15.12 Addition of terminology (Tags)
20.15 Arc-flash Associated with	Section reviewed to reflect current	20.16.3 Addition of 'partial-thickness' burns and NHS reference

	high and low voltage equipment	NHS 2020 definitions	20.16.5 Addition of new section
	20.16 Storage of Batteries: General	Stakeholder engagement comment	20.17 Storage batteries; general 20.17.1 Amended section to follow manufacturer's instructions concerning battery storage.
Chapter 22 – Boarding Arrangements	22.6 Portable and rope Ladders	Reviewed portable rope ladder guidance	22.6.4 Amended 22.6.5 Deleted 22.6.6 Deleted
Chapter 23 – Food Preparation and Handling in the Catering Department	23.1 Health and Hygiene	Reference review	MCA's Wellbeing at Sea: A guide for organisations, Chapter 3.8.1 and Wellbeing at Sea: A pocket guide for seafarers, Chapters 1.1 and 1.2.
Chapter 24 – Hot Work	24.8 Precautions to be taken during electric arc welding	Stakeholder engagement comment	24.8.1 Updated official number references
Chapter 26 - Anchoring, Mooring, and Safe Towing Operations	26.3 Making fast and casting off	Snapback zones – Nautilus Telegraph July 2019 outlining conflicts with advice between COSWP and MAIB's Safety Digest 2019, Case 3	26.3.1 Section reviewed with reference added to the; Effective Mooring (2019, 4th edition) from the Oil Companies International Marine Forum (OCIMF).
			26.3.2 Additional final sentence 'Seafarers other than the mooring parties should keep clear of the mooring decks during mooring and unmooring operations'.
			26.3.3 Added reference to Annex 26.1 of potential snapback zones for illustrative purposes.
			26.3.11 Additional wording added to the section.
			26.3.12 Additional final sentence to highlight the risks when warping a vessel along a berth.
26.6 Safe mooring of domestic passenger craft and ships' launches to quays	Chapter review to reflect the MAIB Reports into the Tug <i>Millgarth</i> 27 January 2019 and the dredger <i>Cherry Sand</i> 28 February 2019.	26.6.4 Amended section ' <i>Passengers and supernumerary personnel must be kept clear of all mooring and unmooring operations and all personnel should keep clear of snap-back zones</i> '. Part of an ongoing section review, with an MGN to be issued outlining guidance, to be incorporated into the next COSWP amendment.	

Appendix 1 - Regulations, Marine Notices and Guidance Issued by the MCA		Out of date or incorrect references amended.	To reflect new MCA wellbeing guidance: Wellbeing at Sea; A pocket Guide for Seafarers and Wellbeing at Sea; A guide for organisations
Appendix 2 - Other Sources of Information		Out of date or incorrect references amended.	Updated website references to latest guidance
Appendix 3 – Standards and Specifications referenced in this Code		Out of date or incorrect references amended.	Updated to the latest British Standard reference numbers

Steve Gomez
Chief Surveyor (Ag)
For & on behalf of the Maritime Administrator

Issue date: 26 April 2021

All notices are available through www.gibraltarship.com

This copy of the Administrative Instruction has been sent electronically and does not carry a signature or official stamp. A sign and stamped copy will be available upon request
