



# Gibraltar Maritime Administration

HM Government of Gibraltar

Watergate House  
2/8 Casemates Square  
Gibraltar

Tel (+350)200 46862 / 200 47771 /200 50424  
Fax (+350) 200 47770  
e-mail: [maritime.survey@gibraltar.gov.gi](mailto:maritime.survey@gibraltar.gov.gi)  
[maritime.registry@gibraltar.gov.gi](mailto:maritime.registry@gibraltar.gov.gi)

## Shipping Guidance Notice – 076 – MARPOL Annex VI – 0.5% Sulphur Cap

---

To: Ship Owners, Operators, Master's, Classification Societies and Recognised Organisations

---

### References:

- Gibraltar Shipping Information Notice 057 – Update Global Sulphur Limits
- MARPOL Annex VI
- IMO MEPC.259(68)
- IMO MEPC.320(74)
- IMO MEPC.321 (74)
- IMO MEPC.1/Circ.878

### 1. INTRODUCTION

The Gibraltar Maritime Administration wishes to remind clients that from 1st January 2020, MARPOL Annex VI requires all fuel used on board ships to have a sulphur content not exceeding 0.5% m/m unless the ship has an equivalent means of compliance.

Within Emission Control Areas (ECAs) the limit remains unchanged at 0.1% m/m sulphur content.

In addition to this, it is prohibited to carry fuel oil with a sulphur content exceeding 0.5% m/m after 1 March 2020 unless an equivalent means of compliance is fitted to the ship.

### 2. EQUIVALENT MEANS OF COMPLIANCE

The GMA is able to accept Exhaust Gas Cleaning Systems (EGCS) as an equivalence under MARPOL Annex VI Regulation 4.1 provided that they are approved by a Recognized Organization in accordance with the IMO guidelines within MEPC.259(68).

Operators using EGCS should be aware of local regulations which may restrict discharge of wash-water within certain areas.

### 3. REPORTING OF NON-AVAILABILITY OF COMPLIANT FUEL

It remains unclear whether there will be sufficient supply of compliant fuel in all ports. If there is not, Annex VI does not require ships to deviate from their intended voyage or to delay their voyage to achieve compliance. Where the only option is to bunker non-compliant fuel, a Fuel non-Availability Report (FONAR) should be submitted to GMA (who will submit this to IMO) and to the

ship's destination port. The standard format for a FONAR, and associated guidance, can be found within MEPC.320(74).

It should also be noted that, if a ship arrives in a port with non-compliant fuel due non-availability of compliant fuel, a port state may request a record of the actions taken to attempt to achieve compliance and evidence that the ship attempted to purchase compliant fuel, so detailed records must be kept in this regard.

#### **4. IMO SHIP IMPLEMENTATION PLAN**

IMO has published a template Ship Implementation Plan for Achieving Compliance with the Sulphur Limit and associated guidance within MEPC.1/Circ.878. Although this is not mandatory, operators should consider the usefulness of completing such a plan, particularly where difficulties are anticipated.

Dylan Cocklan  
Maritime Administrator (Ag)

Issue date: 21 November 2019

All notices are available through [www.gibraltarship.com](http://www.gibraltarship.com)

*This copy of the Administrative Instruction has been sent electronically and does not carry a signature or official stamp. A sign and stamped copy will be available upon enquiry*